

REPUBLIC OF THE PHILIPPINES
OFFICE OF THE PRESS SECRETARY
TANGGAPAN NG KALIHIM PARA SA PRESS
Manila

SUPPLEMENTAL BID BULLETIN NO. 1
11 August 2022

**Supply and Delivery of Motor Vehicle Parts for Repair and Maintenance of
OPS Vehicles**
(Procurement/Contract No. 2022-OPS-070-N)

Anent the Pre-Bid Conference held on 11 August 2022 for the above-cited procurement by the Bids and Awards Committee, please be informed of the following clarifications made and the amendments on the Technical Specifications:

All amendments are indicated in **red**.

COMMENTS/ CLARIFICATION	ANSWER/RESPONSE
Clarification on Technical Specifications, Common Requirements, item no. 2: <i>Guaranteed genuine parts</i> Clarified whether genuine parts of other brands/make will be accepted or specific Toyota parts only.	Genuine Toyota parts. <i>(Please refer to the revised Technical Specifications¹)</i>
Whether the OPS will provide the vehicle chassis number of the concerned vehicles.	Yes. <i>(Please refer to Annex "A")</i>
Clarified the amount of the bidding documents.	The OPS will not apply bidding documents fee since the project is being procured through Negotiated Procurement (Two-Failed Biddings). Prospective Bidders/ Suppliers may download the bidding documents from the PhilGEPS and OPS websites, and participate in the negotiation proceedings, free of cost.
Clarified the manner of bid submission.	Online bid submission. Bids must be submitted via email at bacl@ops.gov.ph not later than 8:00 AM of 18 August 2022.

¹ Please use the attached revised Technical Specifications document in preparing your bid.

Technical Specifications

Bidders must state “**Comply**” in the column “**Statement of Compliance**” against each of the individual parameters of each “Specifications.”

Item No.	*Description	Qty.	Unit of Measure	Statement of Compliance
Motor Vehicle parts for Toyota Innova, compatible with 2008 to 2014 Model (Item Nos. 1 to 10)				
1	Shock Absorber Front, Left and Right	12	sets	
2	Shock Absorber Rear, Left and Right	12	sets	
3	Tie Rod, Left and Right	12	sets	
4	Rack end, Left and Right	12	sets	
5	Ball Joint Upper, Left and Right	12	sets	
6	Ball Joint Lower Left and Right	12	sets	
7	Clutch Disc	12	pieces	
8	Pressure Plate	12	pieces	
9	Release Bearing	12	pieces	
10	Pilot Bearing	12	pieces	
Motor Vehicle parts for Toyota Hi Ace Commuter, 2013 Model (Item Nos. 11 to 24)				
11	Shock Absorber Front, Left and Right	1	set	
12	Shock Absorber Rear, Left and Right	1	set	
13	Tie Rod, Left and Right	1	set	
14	Rack end, Left and Right	1	set	
15	Ball Joint Upper, Left and Right	1	set	
16	Ball Joint Lower, Left and Right	1	set	
17	Clutch Disc	1	piece	
18	Pressure Plate	1	piece	
19	Release Bearing	1	piece	
20	Pilot Bearing	1	piece	
21	Oil Seal (back)	1	piece	
22	Idler Bearing, Big	1	piece	
23	Idler Bearing, Small	1	piece	
24	Brake Pad	1	set	
Common Requirements				
Brand new				
Guaranteed Genuine Toyota Parts				
Warranty period: three (3) months				
Inclusive of all applicable government taxes				
Delivery: To be delivered at the Office of the Press Secretary within thirty (30) calendar days from the receipt of Notice to Proceed				

Conforme:

Signature of Bidder : _____
(Authorized Representative)
over Printed Name : _____
Designation : _____
Name of Company : _____

Pursuant to Section 22.5 of the 2016 Revised Implementing Rules and Regulations of Republic Act No. 9184, this Supplemental/Bid Bulletin is issued for the information and guidance of all prospective bidders and shall form an integral part of the Bidding Documents issued for said the project.

Should you have further concerns, you may contact the BAC Secretariat through the details below:

BIDS AND AWARDS COMMITTEE SECRETARIAT

Office of the Press Secretary
7th Floor, Times Plaza, UN Avenue Manila
Telefax No. (02) 8735-6170
Email: bac1@ops.gov.ph
Website: <https://ops.gov.ph>

For information and guidance.

ORIGINAL SIGNED

USEC. EMERALD R. RIDAO
Chairperson, Bids and Awards Committee

**OFFICE OF THE PRESS SECRETARY
MOTOR VEHICLES**

No.	Vehicle Description	Engine Number	Chassis Number	Year Model
1	TOYOTA INNOVA J DSL MT 2.5 5S	2KD-6311787	KUN40-5029792	2009
2	TOYOTA INNOVA J DSL MT 2.5 5S	2KD-6115468	KUN40-5023290	2008
3	TOYOTA INNOVA E 2.5 DSL M/T	2KD-S286736	KUN40-5102975	2014
4	TOYOTA INNOVA E 2.5 DSL MT	2KD-U259464	KUN40-5092947	2013
5	TOYOTA INNOVA E 2.5 DSL MT	2KD-U259839	KUN40-5092957	2013
6	TOYOTA INNOVA J DSL MT 2.5 5S	2KD-6478384	KUN40-5035589	2010
7	TOYOTA INNOVA E 2.5 DSL MT	2KD-U259687	KUN40-5092971	2013
8	TOYOTA INNOVA J 2.5 DSL MT	2KDU083130	KUN405085689	2012
9	TOYOTA INNOVA V DSL A/T 2.5 5S	2KD-U464787	KUN40-5104196	2014
10	TOYOTA INNOVA J DSL MT 2.5 5S	2KD-U451776	KUN40-5103487	2014
11	TOYOTA INNOVA J DSL MT 2.5 5S	2KD-6127451	KUN40-5023626	2008
12	TOYOTA INNOVA J DSL MT 2.5 5S	2KD-6073985	KUN40-5022244	2008
13	TOYOTA HIACE COMMUTER 2.5 MT DSL	2KD-A087686	JTFJS02P205016462	2013